

Product


FireAngel FE-F600-DE – Löschspraydose

Affected batches

Pack codes – 3617, 3217, 4117, 4317, 4417, 4717, 4817, 4917, 0218 and 0318

Product Identification - Distribution Centre in Shipping Carton

The label on the shipping carton will show the pack code.
The following codes are affected – 3617, 3217, 4117, 4317, 4417, 4717, 4817, 4917, 0218 and 0318



Product Identification – Individual Products no longer in shipping carton



SUSPECT PRODUCTS CAN BE IDENTIFIED AS FOLLOWS. EACH EXTINGUISHER HAS A YELLOW NOZZLE AND IS MARKED ON THE SIDE WITH A MANUFACTURE YEAR OF 2017 - SEP, OCT, NOV, DEC 2017 OR 2018 – JAN, FEB, NOV (PRINT ERROR ON CAN)



Fault

Blocked actuator within the plastic firing mechanism resulting in the extinguisher not discharging its contents in a high percentage of products

Risk

There is no direct risk from the product itself. Extinguishers identified as 'SUSPECT' may not discharge contents when used