

12th March 2018

**Subject: Recall of Multifoam 600ml Aerosol Fire Extinguishers.**

Model numbers and batches suspected to be affected:

AEROSOL 600ML MULTI FOAM FX600MF (Pack code numbers 0618,0818)


AEROSOL 600ML MULTI FOAM FE-F600-AE-UK (Pack code numbers 4917).

AEROSOL 600ML MULTI FOAM FE-F600-FA-BNL (Pack code numbers 4617,  
4717,4817,3617,3717,4117,4217,0618,0718).

AEROSOL 600ML MULTI FOAM FE-F600-DE (Pack code numbers 4117, 3617, 3217,4317, 4417, 4717,  
4817, 4917, 0218 and 0318).

FX Fire suspect that the above batches have been fitted with faulty actuators which may be blocked due to an injection moulding error, potentially causing a malfunction within the firing mechanism, which could result in some units not to discharge. We agree to the recall of these suspect items from customers affected.

We apologise for the inconvenience caused.



James Leete  
Director  
FX Fire and Safety Solutions Ltd.